

Volvo F 88 Leo Bol total Restauration

Allgemeine Merkmale

Marke	Volvo
Modell	F 88
Unterkategorie	Standard SZM
Kennzeichen	DK
Zählerstand	450.000km
Baujahr	1977
Datum der Erstzulassung	23-03-1977
Farbe	Grün
Zustand	Gebraucht
Allgemeiner Zustand	Sehr gut
Kraftstoff	Diesel
Emissionsklasse	Euro 0
Referenz	3319



Eigenschaften

Ledig gewicht	8.500kg
Belastbarkeit	8.000kg
Zulässiges Gesamtgewicht	16.000kg
Kabine	Schlafkabine
Seriennummer	123456789

Technische Spezifikationen

Anzahl der Achsen	2
Achsenkonfiguration	4x2
Übertragung	Schaltgetriebe
Vermögenswerte	350hp

Beschreibung

Registration : 1st registration : Chassis Number : ID Number (Ref. Nr.) : If you need more information or pictures, do not hesitate to contact us! Open Our Stock <https://www.trucksnl.com/company/dan-scan-trucks> and see our fully updated stock Contact Dan Brälye Mobil: +45 20445524 Mail: dan@dan-scan.dk (whatsApp +45 20445524) Location Norgesvej 1 DK6100 Haderslev www.dan-scan.dk <https://www.dan-scan.dk/> Like us on Facebook : <https://www.facebook.com/Dan-Scan-Trucks-DK-107129864586619> Always! on the mobile phone 24 Hour the day We do our best to provide only the correct information in our ads. However, we reserve any errors and wright mistakes in our ad Thanks in advance Dan-Scan trucks (Dan Brälye)